



## Rate comparison of dent occurrence in back chuck 5

(Product Image)



【 Occurrence rate before/after Wavy Nozzle installation】



→ 75% reduce of dent occurrence

- ✓ Machine: NC lathe (C : L16)
- ✓ Coolant: Oil (JIS N3-8)
- ✓ Material: SUS303
- ✓ W/N Mode : Sweep
- ✓ Processing: OD
- ✓ Product Size
  - Length: 29mm
  - Diameter :  $\phi 6.3$